

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

RECEIVED
FEB 10 2000
DIVISION OF
OIL, GAS AND MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) Jan. 1, '99 To (mo./yr.) Dec. 31, '99
 2. DOGM File Number (Mine No): M 10291 001
 3. Mine Name: Devil's Slide Quarry
 4. Mineral(s) Mined (or permitted to mine): Limestone
 5. Type of mine ☒ Surface Mine or ☐ Underground Mine
 6. Legal Description (Location of Lands Affected):
1/4, 1/4, 1/4, Section 19, Township 4N, Range 4E
1/4, 1/4, 1/4, Section 24, Township 4N, Range 4E
1/4, 1/4, 1/4, Section, Township, Range
 7. Name of Operator or Company: Holnam
 8. Permanent Street Address: 6055 E. Croydon Rd.
City, State, Zip: Morgan, Utah 84050
Phone: (801) 829-6821 Fax: (801) 829-2100
 9. Company Representative (or designated operator):
Name: Keith R. Depew
Title: Plant Manager
Business Address: 6055 E. Croydon Rd.
City, State, Zip: Morgan, Utah 84050
Phone: (801) 829-6821 Fax: (801) 829-2100
- ☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? _____
3. If yes - how much ore or mineral was mined? 723,690 m tons Limestone
30,234 m tons Sandstone
753,924 m tons total

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.
Limestone was mined from existing benches
No new surface disturbances
5. How much additional acreage was disturbed during the past year? None
6. How much acreage was reclaimed during the past year? None
7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
8. What is the total disturbed acreage of entire project at years end? 79 acres
9. Briefly summarize any mining and/or reclamation plans for the upcoming year.
Mining is planned with tonnage requirements
similar to 1999.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

Keith R. Depew

Title of Operator:

Plant Manager

Signature of Operator:

[Signature]

Date:

2/2/00